

Certified Repair Sticker

From: Manufacturing

Date: 7-Mar-16

Today Ulterra will begin rolling out all bits repaired in its Fort Worth facility with a “Certified Repair” sticker on the bit can. While most ‘major’ PDC bit companies have a basic certification from API to build new bits, Ulterra is the only company to include repair in our scope of registration. The goal of these stickers is to highlight Ulterra’s commitment to having the highest quality PDC bits in the world.



This PDC bit was repaired in a facility whose quality management system (QMS) is certified and registered as being in conformity with ISO 9001/API Spec Q1. Ulterra is THE ONLY company to include the design, manufacture, AND REPAIR of PDC bits in their scope of registration.

Here are a few points to consider:

- The ISO 9001/API Spec Q1 certifications are over and above the standard API 7-1, which apply only to newly manufactured products.
- These certifications require Ulterra’s facilities to undergo a thorough audit by the American Petroleum Institute (API) every single year to ensure we are operating to the highest quality standards in the industry.
- At least 3 out of every 4 bits run in North America have been repaired, which is why Ulterra has endeavored to include our repair process in our scope of certification and registration.

There is a reason people take their cars to the dealership to get work done and put a premium on Certified Pre-Owned cars – it makes a difference. At Ulterra, EVERY run counts, not just brand new bits.